

DATE: 12/10/2015PROJECT NAME: San Jacinto River Waste PitsPROJECT NO: 150557-01.01**DAILY SAFETY BRIEFING****PERSON CONDUCTING**MEETING: H. Samaha**HEALTH & SAFETY**OFFICER: C. Torell**PROJECT**MANAGER: D. Keith**TOPICS COVERED:**

- | | | |
|--|--|--|
| <input type="checkbox"/> Emergency Procedures and Evacuation Route | <input type="checkbox"/> Lines of Authority | <input type="checkbox"/> Lifting Techniques |
| <input type="checkbox"/> Directions to Hospital | <input checked="" type="checkbox"/> Communication | <input checked="" type="checkbox"/> Slips, Trips, and Falls |
| <input type="checkbox"/> HASP Review and Location | <input checked="" type="checkbox"/> Site Security | <input type="checkbox"/> Hazard Exposure Routes |
| <input checked="" type="checkbox"/> Safety Equipment Location | <input checked="" type="checkbox"/> Vessel Safety Protocols | <input checked="" type="checkbox"/> Heat and Cold Stress |
| <input type="checkbox"/> Proper Safety Equipment Use | <input checked="" type="checkbox"/> Work Zones | <input checked="" type="checkbox"/> Overhead and Underfoot Hazards |
| <input type="checkbox"/> Employee Right-to-Know/MSDS Location | <input checked="" type="checkbox"/> Vehicle Safety and Driving/Road Conditions | <input type="checkbox"/> Chemical Hazards |
| <input type="checkbox"/> Fire Extinguisher Location | <input type="checkbox"/> Equipment Safety and Operation | <input type="checkbox"/> Flammable Hazards |
| <input type="checkbox"/> Eye Wash Station Location | <input checked="" type="checkbox"/> Proper Use of PPE | <input type="checkbox"/> Biological Hazards |
| <input type="checkbox"/> Buddy System | <input checked="" type="checkbox"/> Decontamination Procedures | <input type="checkbox"/> Eating/Drinking/Smoking |
| <input checked="" type="checkbox"/> Self and Coworker Monitoring | <input type="checkbox"/> Other: | |

WEATHER CONDITIONS: sunny, 70°FDAILY WORK SCOPE: inspect cap perimeter;
side scan sonar; test
installation of SPMsSITE-SPECIFIC HAZARDS: uneven terrain
and biological growth on cap;
general diving hazards;
ladder safety for returning
to boat after dive

SAFETY COMMENTS:

ATTENDEES**PRINTED NAME****SIGNATURE**

Holly Samaha	
Neil Heathone	
Brandi Todd	
Valmichael Lewis	
NICK GANNON	
Bill Luthans	
GARY MILLER	



DATE: 12/9/2015PROJECT NAME: San Jacinto River Waste PitsPROJECT NO: 150577-01.01**DAILY SAFETY BRIEFING****PERSON CONDUCTING**MEETING: H. Samaha,**HEALTH & SAFETY**OFFICER: C. Torell**PROJECT**MANAGER: D. KeithTOPICS COVERED: EPA team, N. Hawthorne

- ☐ Emergency Procedures and Evacuation Route
- ☐ Directions to Hospital
- ☐ HASP Review and Location
- ☒ Safety Equipment Location
- ☐ Proper Safety Equipment Use
- ☐ Employee Right-to-Know/MSDS Location
- ☐ Fire Extinguisher Location
- ☐ Eye Wash Station Location
- ☐ Buddy System
- ☒ Self and Coworker Monitoring

- ☐ Lines of Authority
- ☒ Communication
- ☐ Site Security
- ☒ Vessel Safety Protocols
- ☒ Work Zones
- ☒ Vehicle Safety and Driving/Road Conditions
- ☐ Equipment Safety and Operation
- ☐ Proper Use of PPE
- ☒ Decontamination Procedures
- ☐ Other:

- ☐ Lifting Techniques
- ☒ Slips, Trips, and Falls
- ☐ Hazard Exposure Routes
- ☒ Heat and Cold Stress
- ☒ Overhead and Underfoot Hazards
- ☐ Chemical Hazards
- ☐ Flammable Hazards
- ☐ Biological Hazards
- ☐ Eating/Drinking/Smoking

WEATHER CONDITIONS: sunny, 60° F,light windDAILY WORK SCOPE: EPA dive team
visit; inspect cap perimeter;
practice SPME installationSITE-SPECIFIC HAZARDS: uneven
terrain on cap; sharp
shells on
portions of capSAFETY COMMENTS: general dive
team safety issues**ATTENDEES****PRINTED NAME****SIGNATURE**

Alan Humphrey

Brandi Todd

Valmicheal Leos

Gary Miller

Nick Gannon

Phil Stowick

David Keith

Neil Hawthorne

Bill Luthans

Holly Samaha